

## **DZH5000 RECOMMENDED INVENTORY WEAR PARTS LIST**

The following list is a recommended inventory parts list estimated to operate a Diamond Z 5000 horizontal grinder.

<b>QUANTITY</b>	<b>PART NUMBER</b>	<b>DESCRIPTION</b>
250	235251F	Hammer Tips
500	FABLHB14NC5.5	7/8" Grade 8 Bolts
500	FAHN14NC	7/8" Hex Nut
1	12539	Wear Plates
1	12540	Wear Plates
1	12541	Wear Plates
1	12542	Wear Plates
1	12543	Wear Plates
1	12544	Wear Plates
1	12545	Wear Plates
1	12546	Wear Plates
1	12547	Wear Plates
1	12548	Wear Plates
30	FABLPB12NC5.5	Bolts for Wear Plates
30	FALN12NC	Nuts for Wear Plates
2	51202002	Cutter Bar Section
12	FABLFH16NC6	Bolts for Cutter Bars
12	FAHN16NC	Nuts for Cutter Bars
1	408160	Flex Element
1	48037FL	8-Rod Hammer (Left)
1	48037FR	8-Rod Hammer (Right)
1	408151-1	Pillow Blok Bearing (Conveyor)
1	408145	Pillow Block Bearing (Conveyor)
1	11760	Pillow Block Bearing (Pump)
1	670023	Pump Drive Belt
4	PTBLBN914	Mill Drive Belts
1	PTBLBN200738	Mill Drive Belt
2	HYTAFLEL535	Hydraulic Filter (Machine System)
1	2006136	Fluid coupler filter
1	99502020	Omron PLC
2	51200101	Mill Rods
1	99506211	Prox Switch

Note: Call Diamond Z for current pricing. The parts listed above are recommendations only from Diamond Z parts and service professionals. Spare parts orders are at the discretion of Diamond Z equipment owners

It is strongly recommended that as inventory items are sold, a replacement order be made in order to allow for delivery time and minimize freight costs. To ensure proper fit and high quality control standards always use Diamond Z parts.