

## **DZH6000 RECOMMENDED INVENTORY WEAR PARTS LIST**

The following list is a recommended inventory parts list estimated to operate a Diamond Z 6000 horizontal grinder.

<b>QUANTITY</b>	<b>PART NUMBER</b>	<b>DESCRIPTION</b>
2	16445-1	65" 5x7 Rectangle Screen
250	56235251CC	Hammer Tips
500	FABLHB14NC5.5	7/8" Grade 8 Bolts
500	FAHN14NC	7/8" Hex Nut
2	51202002	Cutter Bar Section
12	FABLFH16NC6	Bolts for Cutter Bars
12	FALN16NC	Nuts for Cutter Bars
2	51200101	Mill Rods
2	56203204L	Hammer-Fixed Left
2	56203204R	Hammer-Fixed Right
1	12598-4	Mill Cover Wear Plate Front
1	12323-3	Mill Cover Wear Plate Rear
30	FALPB12NC2.5	Bolts for Mill Cover Wear plates
30	FALN12NC	Nuts for Mill Cover Wear plates
1	PTCPEL408160	Pump Drive Flex Element
2	PTBGPB408145	Pillow Block Bearing (Conveyor)
2	PTBGPB11760	Pillow Block Bearing (Pump)
1	PTBLBN10071	Hydraulic Pump Drive Belt
1	99506211	Proximity Switch
1	HYEL20077	Pressure Switch Kit
1	ELSWLM34451	Limit Switch

Note: Call Diamond Z for current pricing. The parts listed above are recommendations only from Diamond Z parts and service professionals. Spare parts orders are at the discretion of Diamond Z equipment owners

It is strongly recommended that as inventory items are sold, a replacement order be made in order to allow for delivery time and minimize freight costs. To ensure proper fit and high quality control standards always use Diamond Z parts.