

DZH7000 RECOMMENDED INVENTORY WEAR PARTS LIST

The following list is a recommended inventory parts list estimated to operate a Diamond Z
7000 horizontal grinder.

QUANTITY	PART NUMBER	DESCRIPTION
2	16387C	69" 5x7 Rectangle Screens
250	235251CC	Hammer Tips
500	FABLHB14NC5.5	7/8" x 5 1/2" Grade 8 Bolts
500	FAHN14NC	7/8" Hex Nut Grade
2	50202002	Cutter Bar Section
12	FABLFH16NC6	Bolts for Cutter Bars
12	FALN16NC	Nuts for Cutter Bars
1	PTCPEL408160	Pump Drive Flex Element
1	48033FL	Hammer-Fixed Left
1	48033FR	Hammer-Fixed Right
2	12521	Mill Cover Wear Plate Front
1	12599C	Mill Cover Wear Plate Rear
25	FABLPB12NC2.5	Bolts for Mill Cover Wear plates
25	FALN12NC	Nuts for Mill Cover Wear plates
1	PTBGPB408151-1	Pillow Blok Bearing (Conveyor)
1	PTBGPB408145	Pillow Block Bearing (Conveyor)
1	PTBGPB11760	Pillow Block Bearing (Pump)
1	PTBLBN10071	Hydraulic Pump Drive Belt
2	50200101-2	Mill Rods
1	99506211	Proximity Switch
1	HYEL20077	Pressure Switch Kit
1	ELSWLM34451	Limit Switch

Note: Call Diamond Z for current pricing. The parts listed above are recommendations only from Diamond Z parts and service professionals. Spare parts orders are at the discretion of Diamond Z equipment owners

It is strongly recommended that as inventory items are sold, a replacement order be made in order to allow for delivery time and minimize freight costs. To ensure proper fit and high quality control standards always use Diamond Z parts.